

12155.001 - Disc Sander Cookbook

Recommended Tools

Table 1 - Recommended Tools

Function	Minimum	Recommended
Cutting	Reciprocating Power Saw or Abrasive Cut-off Saw (Chop Saw)	Cut-off (Horizontal Band) Saw
Drilling	3/8" Power Drill	1/2" Drill Press
Welding	100 amp Stick Welder	150 amp TIG or MIG Welder
Grinding	4½ " Power Grinder	7" Power Grinder or 9" Power Grinder
Hand Tools	Hammer (16 oz) C-Clamp (6"), two each 6' Tape Measure in Fractions 12" Combination Square Center Punch Automatic Center Punch 1/8" Dia Twist Drill (Pilot Holes) ¼" Dia Twist Drill 5/16" Dia Twist Drill (Tap Drill) 3/8"-16 Tap & Handle Socket Set & Ratchet Handle Open/Box End Wrench Set	Hammer (32 oz) ----- 2 meter or 6' Decimal Tape Measure ----- ----- ----- ----- ----- ----- ----- ----- ----- ----- -----